



# Pictures of Kicker #1 HV Lead Re-insertion

Alexander, Pat, Jenny, Hogan

May 25<sup>th</sup> 2016







View of a High Current Connection Using the Boroscope thru the ~2" port.  
Aluminum Gasket Seal has been crushed. Both high current connections looks good.



Kicker #1: View from the 6" Port to the RIGHT of the HV feedthrough port, looking upstream. Image is UPSIDE DOWN.



Kicker #1: View from the 6" Port to the LEFT of the HV feedthrough port, looking down stream. Image is UPSIDE DOWN.

