


# TPC1: Field Cage HV distribution 6080-003



note on trace and pad sizes:

normal traces are	0.03 inch
wide traces are	0.06 inch
very wide traces are	0.20 inch
normal pt holes are	0.030 inch hole, .08 OD pad
large pt holes are	0.040 inch hole, .10 OD pad
surface contact pas are	0.08 x 0.21 inch