





Technical drawing of a machine assembly. The main view is a cross-section of a cylindrical component with internal features. A detailed view of a specific part is shown on the right, with a leader line pointing to the corresponding feature in the main view.



1

[illegible]

VIEW A-A

[illegible]

VIEW A-A

VIEW A-A

39	Purchased	#10 Washer, SS	41		McMaster-Carr's 96659A104
38	Purchased	#10 Large-OD Washer, SS	226		McMaster-Carr's 90313A103
37	Purchased	#10-32 x 1/2 Button Head Socket Cap Screw, SS	267		McMaster-Carr's 92949A265
36	Purchased	1/4 Washer, 0.625 OD, Thick, 316 SS	8		McMaster-Carr's 91950A029